SAFETY RECALL

Salsa Cycles CroMoto S.U.L. Bicycle Stems

CroMoto S.U.L. Quill and CroMoto S.U.L. Threadless Stems are affected.



Aftermarket stems sold after: April 1, 2010

These stems may crack or break, causing the rider to fall and suffer injuries.

Stems may be identified by a hash mark on the interior clamp portion of the stem body.

Contact your local bicycle retailer to arrange inspection and a free replacement if necessary.

For more information, call Quality Bicycle Products at: (877) 774-6208

Or visit the website at: www.salsacromotostem.com